

Disturbance tracking for exploration project

Drill Holes																
Hole ID	UTM Zone (52/53) and Latitude Band (J, K, L)	Coordinates		Hole Type	Tenement	Is a Drill Pad associated with the drill hole	Is a Sump associated with the drill hole	Drill hole Authorised	Drill hole drilled	If not drilled, is this drill hole still required?	Drill Hole Reahabilitated (hole plugged and cut below ground)	Drill Hole Rehabilitation approved by DITT	Rehabilitated Drill Pad approved by DITT	Was water encountered in confined or multiple aquifers?	Drillhole grouted with concrete	Comments
		Easting	Northing													
RC0001 (example 1)	53K	122345	122345	Reverse Circulation (RC)	EL1234	Yes	Yes	18/10/2020	18/12/2020	Yes	18/12/2020	N/A	N/A	Yes		
DD0002 (example 2)	53K	56790	56790	Diamond Drilling (DD)	EL5678	No	Yes	01/07/2016	02/07/2017	No	18/10/2017	20/12/2018	20/12/2018	No		
MHRC0001	52K	761948	7552979	Reverse Circulation (RC)	EL27892	Yes	No	Oct. 2012	4/11/2012		YES	YES	YES			
MHRC0002	52K	765050	7554048	Reverse Circulation (RC)	EL27892	Yes	No	Oct. 2012	5/11/2012		YES	YES	YES			
MHRC0003	52K	764151	7551401	Reverse Circulation (RC)	EL27892	Yes	No	Oct. 2012	7/11/2012		YES	YES	YES			
MHRC0004	52K	764700	7550509	Reverse Circulation (RC)	EL27892	Yes	No	Oct. 2012	09/11/2012		YES	YES	YES			
MHRC0005	52K	762048	7552851	Reverse Circulation (RC)	EL27892	Yes	No	Oct. 2012	04/11/2012		YES	YES	YES			
MHRC0006	52K	765050	7554053	Reverse Circulation (RC)	EL27892	Yes	No	Oct. 2012	10/11/2012		YES	YES	YES			
MHRC0007	52K	761939	7552981	Reverse Circulation (RC)	EL27892	Yes	No	Oct. 2012	12/11/2012		YES	YES	YES			
MHDD0001	52K	766432	7552941	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	08/03/2013		YES	YES	YES			
MHDD0002	52K	766405	7553004	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	10/03/2013		YES	YES	YES			
MHDD0003	52K	766483	7552968	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	14/03/2013		YES	YES	YES			
MHDD0004	52K	766536	7553017	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	17/03/2013		YES	YES	YES			
MHDD0005	52K	760866	7554801	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	19/03/2013		YES	YES	YES			
MHDD0006	52K	760866	7554801	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	21/03/2013		YES	YES	YES			
MHDD0007	52K	760866	7554801	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	23/03/2013		YES	YES	YES			
MHDD0008	52K	760886	7554706	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	25/03/2013		YES	YES	YES			
MHDD0009	52K	760886	7554706	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	26/03/2013		YES	YES	YES			
MHDD0010	52K	761946	7552979	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	22/03/2013		YES	YES	YES			

MHDD0011	52K	761849	7553098	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	23/03/2013		YES	YES	YES			
MHDD0012	52K	765050	7554050	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	2/04/2013		YES	YES	YES			
MHDD0013	52K	764177	7551451	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	21/03/2013		YES	YES	YES			
MHDD0014	52K	766238	7552929	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	21/03/2013		YES	YES	YES			
MHDD0015	52K	760902	7554549	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2013	19/04/2013		YES	YES	YES			
MHRC0016	52K	760900	7554510	Reverse Circulation (RC)	EL27892	Yes	No	Mar. 2017	12/04/2017		YES	YES	YES			
MHRC0017	52K	760897	7554601	Reverse Circulation (RC)	EL27892	Yes	No	Mar. 2017	14/04/2017		YES	YES	YES			
MHRC0018	52K	761008	7554510	Reverse Circulation (RC)	EL27892	Yes	No	Mar. 2017	15/04/2017		YES	YES	YES			
MHRC0019	52K	760815	7554602	Reverse Circulation (RC)	EL27892	Yes	No	Mar. 2017	17/04/2017		YES	YES	YES			
MHRC0020	52K	766180	7552906	Reverse Circulation (RC)	EL27892	Yes	No	Mar. 2017	18/04/2017		YES	YES	YES			
MHDD0021	52K	761922	7552975	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2017	26/06/2018		YES	YES	YES			
MHDD0022	52K	761753	7553150	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2017	23/04/2017		YES	YES	YES			
MHDD0023	52K	764936	7554051	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2017	28/04/2017		YES	YES	YES			
MHRC0024	52K	764928	7554057	Reverse Circulation (RC)	EL27892	Yes	No	Mar. 2017	30/04/2017		YES	YES	YES			
MHDD0025	52K	761857	7553052	Diamond Drilling (DD)	EL27892	Yes	Yes	Mar. 2017	2/05/2017		YES	YES	YES			
MHRC0026	52K	766364	7552942	Reverse Circulation (RC)	EL27892	Yes	No	Mar. 2017	9/06/2017		YES	YES	YES			
MHRC0027	52K	766400	7552945	Reverse Circulation (RC)	EL27892	Yes	No	Nov. 2017	11/06/2017		YES	YES	YES			
MHRC0028	52K	766185	7552860	Reverse Circulation (RC)	EL27892	Yes	No	Nov. 2017	12/06/2017		YES	YES	YES			
MHDD0029	52K	764930	7554056	Diamond Drilling (DD)	EL27892	Yes	Yes	Nov. 2017	16/06/2017		YES	YES	YES			
MHDD0030	52K	761937	7552962	Diamond Drilling (DD)	EL27892	Yes	Yes	Feb. 2018	1/05/2018		YES					Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.
MHDD0031	52K	761927	7552914	Diamond Drilling (DD)	EL27892	Yes	Yes	Feb. 2018	11/05/2018		YES					Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.
MHDD0032	52K	761927	7552915	Diamond Drilling (DD)	EL27892	Yes	Yes	Feb. 2018	7/05/2018		YES					Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.
MHDD0033	52K	761921	7553001	Diamond Drilling (DD)	EL27892	Yes	Yes	Feb. 2018	3/05/2018		YES					Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.
MHDD0034	52K	764992	7554080	Diamond Drilling (DD)	EL27892	Yes	Yes	Feb. 2018	12/05/2018		YES					Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.

MHDD0035	52K	761921	7552912	Diamond Drilling (DD)	EL27892	Yes	Yes	June 2018	13/06/2018		YES				Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.
MHDD0037	52K	761955	7552835	Diamond Drilling (DD)	EL27892	Yes	Yes	June 2018	17/06/2018		YES				Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.
MHDD0038	52K	761920	7552977	Diamond Drilling (DD)	EL27892	Yes	Yes	June 2018	20/06/2018		YES				Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.
MHDD0039	52K	761922	7552972	Diamond Drilling (DD)	EL27892	Yes	Yes	June 2018	7/07/2018		YES				Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.
MHDD0040	52K	762062	7552873	Diamond Drilling (DD)	EL27892	Yes	Yes	June 2018	16/07/2018		YES				Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.
MHDD0041	52K	761892	7553037	Diamond Drilling (DD)	EL27892	Yes	Yes	Sept. 2018	2/10/2018		YES				Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.
MHDD0042	52K	761887	7553039	Diamond Drilling (DD)	EL27892	Yes	Yes	Sept. 2018	4/10/2018		YES				Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.
MHDD0043	52K	761920	7553065	Diamond Drilling (DD)	EL27892	Yes	Yes	Sept. 2018	5/10/2018		YES				Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.
MHDD0044	52K	761901	7552985	Diamond Drilling (DD)	EL27892	Yes	Yes	Sept. 2018	6/10/2018		YES				Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.
MHDD0045	52K	761895	7552990	Diamond Drilling (DD)	EL27892	Yes	Yes	Sept. 2018	7/10/2018		YES				Most recent site visit by DITT staff was 8 November 2018 when a drill program was in progress - 2018 drillholes had not been fully rehabbed at this time, however sites were left safe and tidy.
MHDD0046	52K	761903	7552941	Diamond Drilling (DD)	EL27892	Yes	Yes	Sept. 2018	28/11/2018		YES				DITT staff have not been to site since November 2018.
MHDD0047	52K	761909	7552984	Diamond Drilling (DD)	EL27892	Yes	Yes	Sept. 2018	30/11/2018		YES				DITT staff have not been to site since November 2018.
MHRC0048	52K	762071	7553091	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2018	2/12/2018		YES				DITT staff have not been to site since November 2018.
MHRC0049	52K	762077	7552981	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2018	3/12/2018		YES				DITT staff have not been to site since November 2018.
MHRC0050	52K	762088	7552932	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2018	4/12/2018		YES				DITT staff have not been to site since November 2018.
MHRC0051	52K	762064	7552945	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2018	5/12/2018		YES				DITT staff have not been to site since November 2018.
MHDD0052	52K	761919	7553063	Diamond Drilling (DD)	EL27892	Yes	Yes	Sept. 2018	7/12/2018		YES				DITT staff have not been to site since November 2018.
MHDD0053	52K	761889	7553008	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	5/03/2019						DITT staff have not been to site since November 2018.
MHDD0053a	52K	761887	7553009	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	7/03/2019						DITT staff have not been to site since November 2018.
MHDD0054	52K	761893	7553005	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	6/03/2019						DITT staff have not been to site since November 2018.
MHDD0055	52K	761852	7553135	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	16/03/2019						DITT staff have not been to site since November 2018.
MHDD0056	52K	761879	7553021	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	28/03/2019						DITT staff have not been to site since November 2018.
MHDD0057	52K	761884	7553019	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	5/04/2019						DITT staff have not been to site since November 2018.
MHDD0058	52K	761858	7553162	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	13/04/2019						DITT staff have not been to site since November 2018.

MHDD0059	52K	761903	7552939	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	21/04/2019									DITT staff have not been to site since November 2018.
MHDD0060	52K	761863	7553160	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	27/04/2019									DITT staff have not been to site since November 2018.
MHDD0061	52K	764929	7554057	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	5/05/2019									DITT staff have not been to site since November 2018.
MHDD0062	52K	764929	7554056	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	5/05/2019									DITT staff have not been to site since November 2018.
MHDD0063	52K	764928	7554057	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	11/05/2019									DITT staff have not been to site since November 2018.
MHDD0064	52K	761013	7554503	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	22/05/2019									DITT staff have not been to site since November 2018.
MHDD0065	52K	760955	7554517	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	27/05/2019									DITT staff have not been to site since November 2018.
MHDD0066	52K	760902	7554505	Diamond Drilling (DD)	EL27892	Yes	Yes	Jan. 2019	30/05/2019									DITT staff have not been to site since November 2018.
MHRC0067	52K	762009	7554368	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	2/10/2019									DITT staff have not been to site since November 2018.
MHRC0068	52K	761992	7554352	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	2/10/2019									DITT staff have not been to site since November 2018.
MHRC0069	52K	761977	7554338	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	3/10/2019									DITT staff have not been to site since November 2018.
MHRC0070	52K	762090	7554019	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	3/10/2019									DITT staff have not been to site since November 2018.
MHRC0071	52K	762077	7554005	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	4/10/2019									DITT staff have not been to site since November 2018.
MHRC0072	52K	762063	7553989	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	5/10/2019									DITT staff have not been to site since November 2018.
MHRC0073	52K	762041	7552784	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	5/10/2019									DITT staff have not been to site since November 2018.
MHRC0074	52K	762023	7552795	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	6/10/2019									DITT staff have not been to site since November 2018.
MHRC0075	52K	762007	7552806	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	10/10/2019									DITT staff have not been to site since November 2018.
MHRC0076	52K	762116	7553990	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	10/10/2019									DITT staff have not been to site since November 2018.
MHRC0077	52K	762104	7553976	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	11/10/2019									DITT staff have not been to site since November 2018.
MHRC0078	52K	762166	7553978	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	12/10/2019									DITT staff have not been to site since November 2018.
MHRC0079	52K	762135	7554006	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	13/10/2019									DITT staff have not been to site since November 2018.
MHRC0080	52K	762142	7553955	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	13/10/2019									DITT staff have not been to site since November 2018.
MHRC0081	52K	762008	7552905	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	14/10/2019									DITT staff have not been to site since November 2018.
MHRC0082	52K	762041	7552924	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	14/10/2019									DITT staff have not been to site since November 2018.

MHRC0083	52K	762057	7552932	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	15/10/2019									DITT staff have not been to site since November 2018.
MHRC0084	52K	763978	7558528	Reverse Circulation (RC)	EL29219	Yes	No	Sept. 2019	15/10/2019									DITT staff have not been to site since November 2018.
MHRC0085	52K	763932	7558539	Reverse Circulation (RC)	EL29219	Yes	No	Sept. 2019	16/10/2019									DITT staff have not been to site since November 2018.
MHRC0086	52K	763918	7558526	Reverse Circulation (RC)	EL29219	Yes	No	Sept. 2019	17/10/2019									DITT staff have not been to site since November 2018.
MHRC0087	52K	763902	7558512	Reverse Circulation (RC)	EL29219	Yes	No	Sept. 2019	17/10/2019									DITT staff have not been to site since November 2018.
MHRC0088	52K	763958	7558506	Reverse Circulation (RC)	EL29219	Yes	No	Sept. 2019	18/10/2019									DITT staff have not been to site since November 2018.
MHRC0089	52K	763947	7558495	Reverse Circulation (RC)	EL29219	Yes	No	Sept. 2019	18/10/2019									DITT staff have not been to site since November 2018.
MHRC0090	52K	763203	7553175	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	19/10/2019									DITT staff have not been to site since November 2018.
MHRC0091	52K	763223	7553177	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	19/10/2019									DITT staff have not been to site since November 2018.
MHRC0092	52K	763166	7553080	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	20/10/2019									DITT staff have not been to site since November 2018.
MHRC0093	52K	763146	7553082	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	20/10/2019									DITT staff have not been to site since November 2018.
MHRC0094	52K	763127	7553084	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	21/10/2019									DITT staff have not been to site since November 2018.
MHRC0095	52K	763126	7553009	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	21/10/2019									DITT staff have not been to site since November 2018.
MHRC0096	52K	763088	7553008	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	22/10/2019									DITT staff have not been to site since November 2018.
MHRC0097	52K	761963	7554385	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	23/10/2019									DITT staff have not been to site since November 2018.
MHRC0098	52K	761936	7554356	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	23/10/2019									DITT staff have not been to site since November 2018.
MHRC0099	52K	761951	7554316	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	24/10/2019									DITT staff have not been to site since November 2018.
MHRC0100	52K	762030	7554337	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	25/10/2019									DITT staff have not been to site since November 2018.
MHRC0101	52K	762009	7554314	Reverse Circulation (RC)	EL27892	Yes	No	Sept. 2019	25/10/2019									DITT staff have not been to site since November 2018.